

Products: GSM Antenna Bracket WA7626-CA.**Subject:** Earth Ground Isolation for Commercial Fire Systems

Back ground: Installations requiring Earth Ground Fault detection, Commercial Fire, are being affected by the inadvertent grounding of the WA7626-CA mounting bracket.

This affects GSM series communicators such as the GSMCF, iGSMCF, or the IPGSM-COM

Solution: Install a nylon shoulder washer under the mounting screws (2x).

It may also be necessary to install tape in-between the bracket and mounting surface, if it is metal.

Drill the 2 mounting holes slightly larger to accommodate the Nylon Shoulder washer.
Use a 7/32 Drill bit, 2 places

