

Oil Light Reset Tool

No. OTC-3596E ~ OTC Oil Light Reset Tool



Oil changes are the #1 service your shop will perform each year. Enhance your service with this complete electronic tool and manual kit, No. 3596E.

Features:

- This kit eliminates the need to take the vehicle to the dealer or use an OEM scan tool to reset oil service lights.
- Electronic tool set includes the adapters and interface module required to reset the oil service lights on Volkswagen, Audi, Mercedes Benz, BMW, and Volvo.
- Updated manual now covers thru 2005 vehicles. Manual includes oil reset tool procedures as well as manual reset procedures for domestic and import vehicles.

Kit Includes:

- No. 3596-1 – **Oil reset monitor.**
- No. 3596-2 – **Mercedes-Benz cable.**
- No. 3596-3 – **BMW cable.**
- No. 3596-4 – **Volvo cable.**
- No. 3596-5 – **VW and Audi cable.**
- No. 3596-6 – **VW and Audi OBD II cable.**
- No. 3596-8 – **Case.**
- No. 3596-9 – **Oil light reset manual.**
- No. 3596-10 – **Battery power adapter cable.**

List of Vehicles Covered:

| | |
|---|---|
| Acura 3.2TL 2001-2005 3.5RL 2001-2005 CL 1997-2003 Integra 1986-2001 Legend 1986-1995 MDX 2001-2005 RSX 2003-2005 RL 1996-2000 TL 1995-2000 TSX 2004-2005 Vigor 1992-1994 | BMW 3 Series (E30, E36) 1988-1999 3 Series (E46) 1994-2000 ½ 3 Series (E46, E83) 2000 ½ - 2005 5 Series (E34, E39) 1988-2000 ½ 5 Series (E39, E53) 2000-2005 5 Series (E60) 2004-2005 6 Series (E63, E64) 2004-2005 7 Series (E32, E38) 1988-2001 7 Series (E65, E66) 2002-2005 8 Series (E31) 1991-1997 M Series (E30, E34, E36) 1988-2000 ½ M Series (E39) 2000 ½ M Series (E39, E46) 2000 ½ -2005 Z3 (E36) 1996-2003 Z4 (E85) 2004-2005 Z8 (E52) 2000-2005 |
| GM/Oldsmobile Alero 1999-2004 Aurora 1995-2003 Bravada 2002-2004 Calais 1988-1991 Custom Cruiser 1982-1991 Cutlass 1982-1991 Cutlass Supreme 1996-1997 Cutlass Ciera 1991-1996 Delta 88 1982-1993 Eighty Eight 1994-1999 Firenza 1982-1988 Intrigue 1998-2002 LSS 1997-1998 Ninety Eight 1982-1996 Omega 1982-1984 Regency 1997 Silhouette 2000-2004 Tornado 1986-1992 | GM/Chevrolet/GMC Camero 1999-2002 Caprice 1994-1996 Cobalt 2005 Colorado/Canyon 2004-2005 Corvette 1982-2005 C-K Series Trucks 1999-2005 Equinox 2005 Express/Savana Vans 2003-2005 Impala 1995-2005 Lumina 1996-2000 Malibu 2004-2005 Monte Carlo 1996-2005 SSR 2004-2005 Trailblazer/Envoy 2002-2005 Venture/Uplander 2000-2005 Pontiac 6000 1985-1991 Aztek 2001-2005 Bonneville 1985-2005 Firebird 1998-2002 G6 2005 Grand Am 1999-2005 Grand Prix 1996-2005 GTO 2004-2005 Montana 2000-2005 |
| Chrysler 300M/Concorde/LHS/New Yorker/Intrepid/Vision 1994-2005 Crossfire 2004-2005 Sprinter 2004-2005 Town and Country/Voyager/ Caravan 2001-2005 | Ford/Lincoln/Mercury Explorer/Mountaineer 1998-2005 Freestyle 2005 LS 2000-2005 Windstar 1998-2003 |
| GM/Cadillac Allante 1989-1993 CTS 2003-2005 Deville 1991-2005 Eldorado 1989-2002 | Jeep Grand Cherokee 1993-2005 Land Rover Defender 1993-1997 |

| | |
|---|---|
| <p>Escalade/Escalade EXT/ Escalade ESV 2002-2005 Fleetwood 1991-1996 Seville 1989-2004 SRX 2004-2005 STS 2005 XLR 2004-2005</p> <p>Honda Accord 1982-2005 Civic 1982-2005 CRX 1984-1991 CRV 1997-2005 Del Sol 1993-1997 Element 2003-2005 Insight 2000-2005 Odyssey 1995-2005 Pilot 2003-2005 Prelude 1982-2002 Odyssey 1995-2002 S2000 2000-2005</p> <p>Hyundai Does not use an oil change reminder light</p> <p>Isuzu Ascender 2003-2005 Oasis 1998-1999 All Other models no oil Change reminder light</p> <p>Jaguar Does not use oil change reminder light</p> | <p>Discovery 1997-2005 Freelander 2002-2005 Range Rover 1990-2005</p> <p>Lexus IS300 2005 LS430 2004-2005 LX470 2005</p> <p>KIA Does not use oil change reminder light</p> <p>Nissan/Infiniti Does not use oil change reminder light</p> <p>Mazda Does not use oil change reminder light</p> <p>Mercedes C-Series/S-Series/SL-Series 1994-1996 C Class 1996-2003 CL Class 1997-2003 CLK Class 1997-2003 E Class 1996-2003 G Class 2002-2003 M Class 1998-2003 S Class 1997-2003 SL Class 1997-2003 SLK Class 1989-2003</p> <p>Mitsubishi Does not use oil change reminder light</p> |
| <p>Nissan/Infinity 350Z 2005</p> | |
| <p>Saturn ION 2003-2005 L Series 2000-2004 Relay 2005 S Series 2000-2002 Vue 2002-2005</p> | <p>Subaru/Suzuki Does not use oil change reminder light</p> <p>Scion Scion 2004-2005</p> <p>Toyota/Lexus Avalon 2004-2005 Camry/Solara/Sienna/Highlander/RAV4/ ES330/IS 300/GX 470/LX470/RX330 2004</p> <p>Corolla/Camry/Matrix/Solara/Highlander/RAV4/Sequoia/ Tacoma/Tundra/Sienna/ES330/GX470/RX330 2005</p> <p>Land Cruiser, 4 Runner 2003-2005 Prius 2004-2005</p> |
| <p>VW/Audi A3 1991-2001 A4 1991-2004 A6 1991-2004</p> | <p>Volvo C70 1998-2004 S40 2000-2005 S60 2001-2005</p> |

| | |
|-----------------------|----------------|
| A8 1991-2005 | S70 1998-2000 |
| A100 1991-1994 | S80 1999-2005 |
| Allroad 2001-2004 | S90 1998 |
| Cabrio 1995-2002 | V40 2000-2004 |
| S4 2000-2004 | V50 2005 |
| TT 2000-2004 | V70 1998-2005 |
| Golf or GTI 1993-1999 | V90 1998 |
| Jetta 1993-1999 | XC70 2001-2004 |
| Passat 1991-2001 | XC90 2003-2005 |
| EuroVan 1999-2001 | 240 1986-1993 |
| New Beetle 1998-2001 | 740 1985-1992 |
| | 760 1987-1990 |
| | 780 1987-1990 |
| | 850 1993-1997 |
| | 940 1991-1995 |
| | 960 1992-1997 |
| | Coupe 1991 |

Manual Sample – Oil Reminder Reset Tool

Honda

Accord

2001-2005

Press the select switch and the reset switch at the same time, turn the ignition switch them for at least 10 seconds, until the indicator resets.

2000

1. Turn off the engine.
2. Press and hold the select/reset button in the instrument panel, then turn the ignition (Position II).
3. Hold the button for at least 10 seconds, until the indicator resets.

1997-1999

With Reset Button on Instrument Panel Press the select switch and the reset switch at the same time, turn the ignition switch them for at least 10 seconds, until the indicator resets.

1997-1999

With Key Slot on Instrument Panel Reset the indicator by inserting your key in the slot beside the indicator.

1992-1996

The indicator is reset to the start of the maintenance interval by inserting the ignition located on the front of the instrument cluster lens. When reset, the indicator's colored green.

1986-1990

If equipped with a service reminder flag, the oil and oil filter service interval will activate after every 7,500 miles of operation. To reset indicators, insert slots below indicator flags at lower right corner of instrument cluster. Push reminder window changes from red to green.

1982-1985

Three maintenance lamps are located on the lower portion of the speedometer service intervals for engine oil, oil filter and other required service. At approximately miles, these maintenance lamps will change from green to yellow, indicating required. After completing the required service, the maintenance lamps inserting the ignition key into the appropriate slot, on the instrument below When the ignition key is inserted into the slot, the indicator lamp should change to green.