

... the heart of your system®



Concorde Battery Corporation  
 2009 San Bernardino Road  
 West Covina, CA 91790  
 Phone (800) 757-0303 or (626) 813-1234  
 Fax (800) 237-4209 or (626) 813-1235  
<http://www.concordebattery.com>

An ISO 9001:2000 Certified Company

### PMA Installation Eligibility List

Revision: EL – 39 (Revised: 3/15/06)

(Contact factory or consult website for latest revision number)

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Battery Part No.	Supplement No.
Aerofab Inc. / REVO	(See Global Amphibians)				
Agusta	A109C, A109E, A119 (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# SR09360RC	RG-407	FAA-PMA Supplement No. 57, dd 06/16/03
Agusta	A109A, A109C, A109E (To replace nickel-cadmium battery)	Rotorcraft Support (818) 997-7667	STC# SR01456LA	RG-407	FAA-PMA Supplement No. 62, dd 10/30/03
Alon	(See Univair)				
American Champion	7ECA, 7GCAA, 7KCAB	American Champion (800) 223-9381 (262) 534-6315	TC# A-759	RG-25	FAA-PMA Supplement No. 31, dd 06/03/97
American Champion	8GCBC, 8KCAB	American Champion (800) 223-9381 (262) 534-6315	TC# A-21CE	RG-25	FAA-PMA Supplement No. 31, dd 06/03/97
Aviat Inc. / Sky International	Aviat Model A-1A, A-1B Aviat Pitts Model S-2C	Aviat Inc. / Sky International (307) 885-3151	TC# A22NM & A8SO	RG-25	FAA-PMA Supplement No. 42, dd 08/06/01
Aviat Inc. / Sky International	Aviat Model A-1 Aviat Pitts Models S-1S, S-1T, S-2, S-2A, S-2S, S-2B	Aviat Inc. / Sky International (307) 885-3151	TC# A22NM & A8SO	RG-25	FAA-PMA Supplement No. 18, dd 08/02/95
Bell	206A & 206B (To replace nickel-cadmium battery)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00318SE	RG-206	FAA-PMA Supplement No. 26, dd 06/21/96
Bell	206A & 206B (To replace nickel-cadmium battery)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC & STA# SR09054RC	RG-206	FAA-PMA Supplement No. 23, dd 04/04/96
Bell	204B, 205B, 205A-1, 212, 412 (To replace nickel-cadmium battery)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00173SE	RG-380E/44*	FAA-PMA Supplement No. 20, dd 11/13/95
Bell	212 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44* or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92
Bell	214ST (To replace nickel-cadmium battery) (Battery & STC avail. through STC holder)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC# SR09225RC	RG-214	FAA-PMA Supplement No. 45, dd 10/22/02
Bell	222U (To replace nickel-cadmium)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC# SR09142RC	RG-380E/44*	FAA-PMA Supplement No. 30, dd 05/18/97
Bell	212, 412, 412EP (To replace nickel-cadmium battery)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC & STA# SR09053RC	RG-380E/44*	FAA-PMA Supplement No. 23, dd 04/04/96
Bell	206L-1, 206L-3, 206L-4 (To replace nickel-cadmium battery)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC & STA# SR09069RC	RG-222	FAA-PMA Supplement No. 25, dd 06/07/96
Bell	206L, 206L-1, 206L-3, 206L-4 (To replace nickel-cadmium battery)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00462SE	RG-222	FAA-PMA Supplement No. 48, dd 12/02/02
Bell	407 (To replace nickel-cadmium battery) (Battery & STC avail. through STC holder)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC# SR09359RC	RG-407A1	FAA-PMA Supplement No. 58, dd 06/19/03
Bell	407 (STC to replace nickel-cadmium battery)	Rotorcraft Support (818) 997-7667	STC# SR01456LA	RG-407	FAA-PMA Supplement No. 62, dd 10/30/03
British Aerospace	Jetstream 3101 (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# SA2994SO	RG-390E	FAA-PMA Supplement No. 16, dd 05/18/92
British Aerospace	Jetstream 3201 (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# SA2995SO	RG-390E	FAA-PMA Supplement No. 16, dd 05/18/92
British Aerospace	Jetstream 3201 (S/N: 790 - 9999) (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# ST00342LA	RG-380E/44* or RG-380E/40B	FAA-PMA Supplement No. 32, dd 06/11/97

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Battery Part No.	Supplement No.
Cessna	150, 152, A/F/F/A 152, 172, 172A, P/R 172, 175, 188, 310, 310G/L, 320, 320D/E, 340	Concorde Battery (800) 757-0303	FAA Design Approval	CB-25	FAA-PMA Supplement No. 8, dd 03/03/88
Cessna	150, 150A, 150B, 150C, 150D, 150E, 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, 152, A152, 120, 140, 140A, 170, 170A, 170B, 172, 172A, 172B, 172C, 172D, 172E, 172F, 172G, 172H, 172I, 172K, 172L, 172M, 172N, 172P, 172Q, 172R, 172S, 175, 175A, 175B, 175C, P172D, R172E, R172F, R172G, R172H, R172J, R172K, 172RG, 177, 177A, 177B, 177RG, 180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K, 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, R182, TR182, 182S, 182T, T182, T182T, 185, 185A, 185B, 185C, 185D, 185E, A185E, A185F, 188, A188, A188A, 188B, A188B, T188C, 206, 206H, U206, P206, T206H, U206A, P206A, P206B, TU206A, TU206B, TP206A, TP206B, U206B, P206C/TP206C, P206D/TP206D, P206E/TP206E, U206C/TU206C thru U206G/TU206G, 207, 207A, T207, T207A, 305B, 305E, 210, 210A, 210B, 210C, 210D, 210E, 210F, T210F, 210G, T210G, T210H, 210H, T210J, 210J, 210K, T210K, 210L, T210L, 210M, T210M, 210N, P210N, T210N, 210R, P210R, T210R, 210-5 (205), 210-5A (205A), 337, 337A thru 337H, T337B to T337F, T337H, M337B, P337H, T337H-SP	Concorde Battery (800) 757-0303	STC# SA01118WI	CB-25 CB-25XC RG-25 RG-25XC Replaces original battery p/n 0511319-1  CB-35A CB-35AXC RG-35A RG-35AXC Replaces original battery p/n 0712605-1 or 0712604-1 or 0311053  CB-24-11 CB-24-11XC RG-24-11 RG-24-15 Replaces original battery p/n C614001-0106  CB-24-11M CB-24-11MXC RG-24-11M RG-24-15M Replaces original battery p/n C614002-0102	FAA-PMA Supplement No. 46, dd 10/25/02
Cessna	152, A152, 172, 177, 177RG, 180, 182, T182, 185, A188, 210, P210, T210, 337, P337, T337	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-11	FAA-PMA Supplement No. 5, dd 05/18/82
Cessna	210 (S/N: 21059503 & on), T210	Wilco (800) 767-7593 (316) 943-9379	STC# SA2558CK	RG24-11M	FAA-PMA Supplement No. 14, dd 02/07/91
Cessna	172, R172, 172RG, 182, T182, R182, TR182, T303	Concorde Battery (800) 757-0303	FAA Design Approval	RG24-11M	FAA-PMA Supplement No. 13, dd 03/16/89
Cessna	182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, R182/TR182, 182R/T182 (182 Series through S/N: 18265965 Except: 18263479)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00753WI	CB-35A RG-35A RG-35AXC	FAA-PMA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02
Cessna	182 Series (S/N:18263479, 18265966 and up), R182 and TR182 Series (S/N: R18200001 and up)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00753WI	RG24-15	FAA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02
Cessna	425 (Conquest I) (To replace nickel-cadmium battery)	Wilco (800) 767-7593 (316) 943-9379	STC# SA2435CE	RG-380E/44*	FAA-PMA Supplement No. 14, dd 02/07/91
Cessna	425 (To replace nickel-cadmium battery)	Wilco (800) 767-7593 (316) 943-9379	STC# SA2436CE	CB24-380E	FAA-PMA Supplement No. 14, dd 02/07/91
Cessna	441 (Conquest II) (To replace nickel-cadmium battery)	Wilco (800) 767-7593 (316) 943-9379	STC# SA2496CE	RG-380E/44*	FAA-PMA Supplement No. 14, dd 02/07/91
Cessna	441 (Conquest II) (To replace nickel-cadmium battery)	Wilco (800) 767-7593 (316) 943-9379	STC# SA2247CE	CB24-380E	FAA-PMA Supplement No. 14, dd 02/07/91

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Battery Part No.	Supplement No.
Cessna	120, 140, 140A, 170, 170A, 170B, 172 thru 172Q, 172R, 172S, 210, 210A thru 210R, T210F thru T210R, P210N, P210R, 210-5, 210-5A, 175, 175A, 175B, 175C, 172RG, P172D, R172E, R172F thru R172K, 177, 177A, 177B, 177RG, 180, 180A thru 180K, 185, 185A thru 185E, A185E, A185F, 188, 188A, 188B, A188, A188A, A188B, T188C, 206, U206, P206, U206A, P206A, P206B, TU206A, TU206B, TP206A, TP206B, U206B, P206C/TP206C thru P206E/TP206E, U206C/TU206C thru U206G/TU206G, 206H, 207, 207A, T207, T207A, 305B, 305E, 337, 337A thru 337H T337B thru T337H, M337B, P337H, T337H-SP, 150, 150A thru 150M, A150K thru A150M, 152, A152	Wilco (800) 767-7593 (316) 943-9379	STC# SA00897WI	RG-25 or RG25XC Replaces original battery p/n 0511319-1  RG-35A or RG35AXC Replaces original battery p/n 0712605-1  RG24-11 RG24-15 Replaces original battery p/n C614002-0102  RG24-11M RG24-15M Replaces original battery p/n C614001-0106	FAA-PMA Supplement No. 43, dd 09/04/01
Cessna	550 (Citation II) Series (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# ST01639LA	RG-131	FAA-PMA Supplement No. 72 dd 06/24/04
Cessna	(Caravan) 208, (Citation II) 500, 501, 550, 551 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Cessna	(Caravan) 208, 425, 441, (Citation II) 500, 501, 550, 551 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44* or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92
Cirrus	SR20, SR22	Concorde Battery (800) 757-0303	STC# SA01304WI	CB24-11M, CB24-11MXC, RG24-11M, RG24-15M	FAA-PMA Supplement No. 76, dd 02/18/05
Dassault	Falcon 10 (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# ST00774LA	RG-390E	FAA-PMA Supplement No. 39, dd 04/23/99
Dassault	Falcon 20 Series, C, D, E, F (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Dassault	Falcon 20 Series, C, D, E, F (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44* or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92
Dassault	MF 50 (To replace nickel-cadmium battery) (Battery Modification available through Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E/LS	FAA-PMA Supplement No. 51, dd 02/21/03
Dassault	Falcon MF900, F900EX (To replace nickel-cadmium battery) (Battery Modification available through Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E/LS	FAA-PMA Supplement No. 51, dd 02/21/03
Dassault	Falcon 2000 (To replace nickel-cadmium battery) (Battery Modification available through Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44LS	FAA-PMA Supplement No. 51, dd 02/21/03
Embraer	EMB-110P1, EMB-110P2 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Embraer	EMB-110P1, EMB-110P2 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44* or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92
Enstrom Helicopter	F-28F & 280FX	Enstrom Helicopter (906) 863-1200	TC# H1CE, Rev. 20, Rev. A	RG24-11M (24V) & RG-35A (12V)	FAA-PMA Supplement No. 23, dd 04/04/96
Erco / Ercoupe	(See Univair)				

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Battery Part No.	Supplement No.
Eurocopter	AS350 B, BA, B1, B2, B3, D (To replace p/n 151CH-1 nickel-cadmium battery as a substitute for p/n 1606-1 as covered on American Eurocopter STC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-350	FAA-PMA Supplement No. 52, dd 02/18/03
Eurocopter	AS350 B, B1, B2, BA, C, D, D1 (To replace p/n 1606-1 nickel-cadmium battery)	Falcon Crest (800) 833-5422 (713) 644-2290	STC# SR09185RC	RG-355	FAA-PMA Supplement No. 35, dd 03/06/98
Eurocopter	AS355 E, F, F1, F2, N (To replace p/n 1606-1 nickel-cadmium battery)	Falcon Crest (800) 833-5422 (713) 644-2290	STC# SR09186RC	RG-355	FAA-PMA Supplement No. 35, dd 03/06/98
Eurocopter	BK-117-A-1, -A-3, -A-4, -B-1, -B-2, -C-1 (To replace nickel-cadmium battery)	Falcon Crest (800) 833-5422 (713) 644-2290	STC & STA# SR09034RC	RG-390E	FAA-PMA Supplement No. 21, dd 11/15/95
Eurocopter	BO-105C & BO-105S (To replace nickel-cadmium battery)	Falcon Crest (800) 833-5422 (713) 644-2290	STC# SR09016RC	RG-390E	FAA-PMA Supplement No. 21, dd 11/15/95
Fairchild Aircraft	(See M-7 Aerospace)				
Garlick Helicopters	Bell UH-1F, UH-1P, TH-1F (To replace nickel-cadmium battery)	Tamarack Helicopters (406) 777-1044	STC# SR01394LA	RG-390E	FAA-PMA Supplement No. 53, dd 03/26/03
Global Amphibians	LA-4, LA-4-200, Model 250 (S/N: 1-25 only)	Global Amphibians (Phone unknown)	FAA Design Approval	RG-35A or RG-35AXC	FAA-PMA Supplement No. 25, dd 06/07/96
Globe	GC-1A, GC-1B	Swift Museum Foundation (423) 745-9547	TC# A-766	RG-35A	FAA-PMA Supplement No. 63, dd 10/30/03
Grumman Aircraft	(See Tiger Aircraft)				
Gulfstream Aerospace	Israel Aircraft Ind. Galaxy/Gulfstream 200 (To replace part no. 414377)	Gulfstream Aero. (214) 902-7770	FAA Design Approval	RG-380E/44C RG-380E/60C	FAA-PMA Supplement No. 56, dd 05/27/03
Gulfstream Aerospace	Israel Aircraft Ind. Galaxy/Gulfstream 200 (To replace part no. 2778-18)	Gulfstream Aero. (214) 902-7770	FAA Design Approval	RG-390E/C	FAA-PMA Supplement No. 56, dd 05/27/03
Gulfstream Aerospace	Israel Aircraft Ind. Galaxy/Gulfstream 200 (Temperature Sensor)	Gulfstream Aero. (214) 902-7770	FAA Design Approval	5-0054 (CBC Kit #TS-C2)	FAA-PMA Supplement No. 56, dd 05/27/03
Gulfstream Aerospace (Also see Twin Commander)	(Gulfstream I) G-159 (Aerocommander) 690B, 695, 695A, 695B (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Gulfstream Aerospace (Also see Twin Commander)	(Gulfstream I) G-159 (Aerocommander) 680T, 680V, 680W, 690, 690A, 690B, 690C, 690D, 695, 695A, 695B (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44* or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92
Gulfstream Aerospace (Also see Twin Commander)	G-1159, G-1159A, G-1159B (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# ST00773LA	RG-380E/44*	FAA-PMA Supplement No. 40, dd 04/30/99
Gulfstream Aerospace (Also see Twin Commander)	G-1159A, G-IV (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# ST00544LA	RG-380E/44*	FAA-PMA Supplement No. 38, dd 11/02/98
Israel Aircraft	(Jet Commander) 1121, 1121A, 1121B (Westwind) 1123, 1124 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Israel Aircraft	(Jet Commander) 1121, 1121A, 1121B (Westwind) 1123, 1124 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44* or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92
JetProp LLC	Piper PA-46-310P, PA-46-350P	Rocket Eng. / Jet Prop LLC (509) 535-4401	STC# ST00541SE	RG-46	FAA-PMA Supplement No. 54, dd 04/29/03

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Battery Part No.	Supplement No.
JetProp LLC	Piper PA-46-310P, PA-46-350P (Higher Capacity Replacement)	Rocket Eng. / Jet Prop LLC (509) 535-4401	STC# ST00541SE	RG-49	FAA-PMA Supplement No. 54, dd 04/29/03
Kaman Aerospace	K1200	Concorde Battery (800) 757-0303	TC# TR7BO	RG-380E/40B	FAA-PMA Supplement No. 26, dd 06/21/96
Kelowna Flightcraft	Convair 440	Concorde Battery (800) 757-0303	FAA Design Approval	CB 12-88	FAA-PMA Supplement No. 6, dd 07/16/82
Lanshe Aerospace	(See Global Amphibians)				
LearJet	23, 24, 25, 28, 29, 35, 36 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
LearJet	23, 24, 25, 28, 29, 35, 36, 55 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44* or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92
LearJet	45 (To replace lead-acid battery) (STC for emergency battery only)	Concorde Battery (800) 757-0303	STC# ST01173WI	RG-443	FAA-PMA Supplement No. 59, dd 06/23/03
LearJet	55	Ni-Cad Systems (510) 785-9391	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 14, dd 02/07/91
M-7 Aerospace	Fairchild SA226-AT, SA227-AT, SA226-T, SA227-CC, -DC (RG-390ES replaces M-7 Aerospace p/n FASRG390ESTC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390ES	FAA-PMA Supplement No. 60, dd 06/25/03
M-7 Aerospace	Fairchild SA226-T, SA226-T(B), SA227-TT (To replace p/n RG-91A which replaces M-7 Aerospace p/n FASRG91STC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-91	FAA-PMA Supplement No. 69, dd 05/17/04
Maule Aerospace Technology Inc.	M-4-210, M-4-220, M-4-180, M-5-180, M-5-210, M-5-220, M-5-235, M-5-210TC, M-5-200, M-6-180, M-6-235, M-7-235, M-7-235A, M-7-235B, M-7-235C, M-7-260, M-7-260C, M-8-235, MT-7-235, MT-7-260, MX-7-160, MX-7-160C, MX-7-180, MX-7-180A, MX-7-180B, MX-7-180C, MX-7-180AC, MX-7-235, MXT-7-160, MXT-7-180, MXT-7-180A	Maule Aerospace (229) 985-2045	FAA Design Approval	RG-35A RG-35AXC	FAA-PMA Supplement No. 64, dd 01/06/04
MD Helicopter	MD369, 369A, 369D, 369F, 369FF, 369H, 369HM, 369HS, 369HE, 369E and 500N (To replace nickel-cadmium battery)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00716SE	RG-500 Connector: CBP-3349-2W Adaptor: 9542	FAA-PMA Supplement No. 47, dd 12/02/02
MD Helicopter	600N (To replace nickel-cadmium battery with the connector receptacle on right side of battery container – Used for most 600N models)	Concorde Battery (800) 757-0303	STC# SR01564LA	RG-600-1 Connector: CBP-3349-2W Adaptor: 9542	FAA-PMA Supplement No. 67, dd 02/06/04
MD Helicopter	600N (To replace nickel-cadmium battery with the connector receptacle on left side of battery container)	Concorde Battery (800) 757-0303	STC# SR01564LA	RG-600-2 Connector: CBP-3349-2W Adaptor: 9542	FAA-PMA Supplement No. 67, dd 02/06/04
Mitsubishi	MU-2B, MU-2B-10, -15, -20, -25, -26, -26A, 30, 35, 36, 36A, 40, 60, MU-300-1, -1A (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44* or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92
Mitsubishi	YS-11A Series (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# SA2795SO	RG-390E	FAA-PMA Supplement No. 15, dd 01/06/92

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Battery Part No.	Supplement No.
Mooney	M20 (w/ R-33 or R-35 battery), M20A (w/ R-33 or R-35 battery), M20B, -20C, -20D, -20E, -20F, M20G, M20J (S/N 24-0001 to 24-2999), M20K (S/N 25-0001 to 25-0999)	Concorde Battery (800) 757-0303	Identity per 14 CFR § 21.303	RG-35A (To replace R-33) or RG-35AXC (To replace R-35)	FAA-PMA Supplement No. 77, dd 03/01/05
Mooney	M20J, M20K	STC/Mooney Ltd. (830) 792-2918	STC# SA00081SE & STC# SA5691NM	RG-35A	FAA-PMA Supplement No. 24, dd 05/06/96
Piaggio Aero Industries SpA	P180	Concorde Battery (800) 757-0303	STC# SA01653LA	Battery: RG-380E/40L Temp. Sensor: TS-C6A (Selling p/n 5-0242)	FAA-PMA Supplement No. 74, dd 09/27/04
Pilatus Britten Norman Ltd.	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A- 27, BN-2B-20, BN-2B-21, BN-2B-26, BN- 2B-27, BN-2T, BN-2T-4R	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E or CB24-3151E	FAA-PMA Supplement No. 34, dd 11/18/97
Pilatus	PC-12 (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# ST00776LA	RG-380E/44*	FAA-PMA Supplement No. 39, dd 04/30/99
Piper	PA-12, PA-12S, PA-18, PA-18 "105" (Special), PA-18 "125" (Army L-21B), PA-18 "135" (Army L-21B), PA-18 "150", PA-18A, PA-18A "135", PA-18A "150", PA-18S, PA-18S "105", PA-18S "125", PA- 18S "135", PA-18S "150", PA-18AS "125", PA-18AS "135", PA-19 (Army L-18C), PA-19S, PA-20, PA- 20 "115", PA-20 "135", PA-20S, PA-20S "115", PA-20S "135", PA-22, PA-22-108, PA-22-135, PA-22-150, PA-22-160, PA-22S-135, PA-22S-150, PA-22S-160, PA-23, PA-23-160, PA-23-235, PA-23-250 (Navy UO-1), PA-E23-250, PA-24, PA-24-250, PA-24-260, PA-25, PA-25-235, PA-25-260, PA-28-140, PA-28-150, PA-28-151, PA-28-160, PA-28-161, PA-28-180, PA-28-181, PA-28-201T, PA-28-235, PA-28-236, PA-28R-180, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-28S-160, PA-30, PA-31, PA-31-300, PA-31-350 & T-1020, PA-31-325 C/R, PA-32-260, PA-32-300, PA-32-301, PA-32-301T, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301, PA-32R-301T, PA-34-200, PA-34-200T, PA-34-220T, PA-36-285, PA-36-300, PA-36-375, PA-36-285, PA-38-112, PA-39, PA-40, PA-44-180, PA- 44-180T TURBO, PA-46-310P, PA-46-350P, PA-60-600, PA- 60-601, PA-60-601P, PA-60-602P, PA-60-700P, PA-400	Concorde Battery (800) 757-0303	STC# SA01147WI	CB-25 CB-25XC RG-25 RG-25XC Replaces original battery p/n 450-030 Use RG-25 only to replace p/n 450-022  CB-35A CB-35AXC RG-35A RG-35AXC Replaces original battery p/n 450-027 or 450-032  CB24-11 CB24-11XC RG24-11 RG24-15 Replaces original battery p/n 450-027 or 450-032  CB24-11M CB24-11MXC RG24-11M RG24-15M Replaces original battery p/n 450-101  RG24-20 Replaces original battery p/n 450-028, 450- 031 or 450-029	FAA-PMA Supplement No. 50, dd 3/7/03

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Battery Part No.	Supplement No.
Piper	PA-12, PA-12S PA-18, PA-19 (Army L-18C), PA-18 "125" (Army L-18A) , PA-18 "135" (Army L-21B), PA-18A, PA-18A "135", PA-18 "105", PA-18S, PA-19S, PA-18S "125", PA-18S "135", PA-18AS "125", PA-18AS "135", PA-18S "105", PA-18 "150", PA-18A "150", PA-18S "150", PA-18A, PA-18A "135", PA-18A "150" PA-20, PA-20 "115", PA-20S, PA-20S "115", PA-20S "135", PA-20 "135", PA-22, PA-22-135, PA-22S-135, PA-22-150, PA-22S-150, PA-22-160, PA-22S-160, PA- 22-108, PA-24, PA-24-250, PA-24-400, PA-24-260, PA-25, PA-25-235, PA-25-260, PA-23, PA-23, PA-23-160, PA-23-250 (Navy UO-1), PA-28-160, PA-28-150, PA-28-180, PA-28S-160, PA-28S-180, PA- 28-235, PA-28-140, PA-28R-200, PA-28-151, PA-28-181, PA-28-161, PA-28R-201, PA-28R-201T, PA-28-236, PA-28RT-201, PA-28RT-201T, PA-28-201T, PA-32-260, PA-32-300, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301 (SP), PA-32R-301 (HP), PA-32R-301T, PA-32-301, PA-32-301T, PA-38-112, PA-36-285, PA-36-300, PA-36-375, PA-46-310P, PA-46-350P	Wilco (800) 767-7593 (316) 943-9379	STC# SA00954WI	RG-25 or RG-25XC Replaces original battery p/n 450-030  RG-35A or RG-35AXC Replaces original battery p/n 450-035  RG24-11 or RG24-15 Replaces original Battery p/n 450-032  RG24-11M or RG24-15M Replaces original battery p/n 450-101  RG24-20 Replaces original battery p/n 450-031	FAA-PMA Supplement No. 43, dd 09/04/01
Piper	PA-23 Apache, PA-23-160, PA-23-250 (Navy UO-1), PA-23-235, PA-E-23-250 Aztec, PA-23-250, PA-31 Navajo, PA-31- 300 Navajo, PA-31-350 Chieftan & T-1020, PA-31-325 Navajo C/R, PA-44-180 Seminole, PA-44-180T Turbo Seminole, PA-30 Twin Comanche, PA-39 Twin Comanche, PA-40 Twin Comanche, PA- 34-200 Seneca, PA-34-200T Seneca II, PA-34-220T Seneca III, IV, V	Wilco (800) 767-7593 (316) 943-9379	STC# SA00954WI	RG-25 or RG-25XC Replaces P/N 450-030  RG-35A or RG-35AXC Replaces P/N 450-035  RG24-11 or RG24-15 Replaces P/N 450-032  RG24-11M or RG24-15M Replaces P/N 450-101  RG24-20 Replaces P/N 450-031	FAA-PMA Supplement No. 61, dd 07/14/03
Piper	(Cheyenne) PA-31T, PA-31T1, PA-31T2, PA-31T3, PA-42, PA-42-720, PA-42-1000 (To replace nickel-cadmium battery)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00843WI	RG-380E/44L RG-380E/44K RG-380E/60L RG-380E/60K	FAA-PMA Supplement No. 80, dd 12/02/05
Piper	PA-46-500TP	Concorde Battery (800) 757-0303	FAA Design Approval	RG-45 & RG-47	FAA-PMA Supplement No. 66, dd 01/15/04
Raytheon	F33A, F33C, V35B, A36, A36TC	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-11	FAA-PMA Supplement No. 5, dd 05/18/82
Raytheon	77	Concorde Battery (800) 757-0303	FAA Design Approval	CB-25	FAA-PMA Supplement No. 1, dd 03/03/81 Amended: dd 03/03/88
Raytheon	MU-300-10, 400, 400A (To replace nickel-cadmium battery)	Raytheon A/C Svc (800) 256-6012 (404) 699-9228	STC# SA2494SO	RG-380E/40B	FAA-PMA Supplement No. 22, dd 01/23/96
Raytheon	A200CT (Military) RC-12K	Wilco (800) 767-7593 (316) 943-9379	FAA Design Approval	TS-C6 Temp. Sensor (Selling p/n 5- 0125)	FAA-PMA Supplement No. 70, dd 05/28/04

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Battery Part No.	Supplement No.
Raytheon	Kingair 65-90, 65-A90, B90, C90, E90, F90, 99, A100, B100, 200, 300, MU-300-10, 400, 400A, 400T, (T-1A) Concorde (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44* or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92
Raytheon	Kingair 65-90, 65-A90, 65-A90-1 (JU-21A, U-21A, RU-21A, RG-21D, U-21G, RU-21H), 65-A90-4 (RU-21E, RU-21H), B90, C90, 65-A90-2 (RU-21B), 65-A90-3 (RU-21C), E90, H90 (T-44A), C90A, F90, 99, 99A, 99A (FACH), 100, A99, A99A, A100 (U-21F), B99, A100A, B100, C99, 200 (A100-1(U-21J)), A200C (UC-12B), 200C, B200, B200C (C-12F, UC-12F, UC-12M, C-12R), A200 (C-12A, C-12C), 200T, 200CT, A200CT (C-12D, C-12F, FWC-12D, RC-12D, RC-12F, RC-12G, RC-12H, RC-12K, RC-12P, RC-12Q), B200CT, B200T, 300, 300LW, B300, B300C, 1900, 1900C, 1900C (C-12J), 1900D (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# SA01260WI	RG-380E/40L RG-380E/40K RG-380E/44L RG-380E/44K RG-380E/60L RG-380E/60K	FAA-PMA Supplement No. 73, dd 08/11/04
Raytheon	Kingair 65-90, 65-A90, 65-A90-1 (Military U-21A, RU21A, RU21D, JU21A, U-21G, RU21H/GRV), 65-A90-4 (Military RU21E, RU21H/GRV & IV), B90, C90, 65-A90-2 (Military RU-21B), 65-A90-3 (Military RU-21C), E90, H90, (Military T-44A), C90A, F90, 99 & 99A, (Military 99A), 100, A99, A99A, A100 (Military U-21F), B99, A100A, B100, C99, 200, A200C, (Military UC-12), 200C, B200, B200C, (Military C12F, UC-12F & UC-12M), A200 (Military C-12A, C-12C), 200T, 200CT, A200CT (Military C-12D, FWC-12D, RC-12D, C-12F, RC-12G, RC-12H), B200CT, B200T, 200T, A100-1 (Military U-21J), A200CT (Military RC-12K), 1900, 1900C (Bladder Fuel), 1900C (Wet Wing), 1900C (Military C-12J), 1900D, 300, 300LW, B300, B300C, (S/N: FM-1 & subsequent, FN-1 & subsequent) (To replace nickel-cadmium battery)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00741WI	RG-380E/40K RG-380E/44K RG-380E/44L RG-380E/60K	FAA-PMA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02
Raytheon	65-90, 65-A90, B90, C90, E90, F90, 99, A100, B100, B200 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Raytheon	200, 300, & B300 Series (To replace nickel-cadmium battery)	Raytheon A/C Svc (800) 256-6012 (404) 699-9228	STC# SA2699SO	RG-380E/40B	FAA-PMA Supplement No. 22, dd 01/23/96
Raytheon	BAe 125-800A (To replace lead-acid battery)	Concorde Battery (800) 757-0303	STC# SA2984SO	RG-390E	FAA-PMA Supplement No. 15, dd 01/06/92
Raytheon	400A (S/N RK-98 and after) (Replaces a nickel-cadmium battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40L	FAA-PMA Supplement No. 49, dd 1/23/03
Raytheon	Hawker 1000 (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# ST00640LA	RG-380E/60K	FAA-PMA Supplement No. 39, dd 04/23/99
Raytheon	BH.125 Series 1A, 1A/522, 1A/R-522, 1A/S-522; Series 3A, 3A/R, 3A/RA, BH.125 400A, 600A, HS.125 600A, 700A, BAe 125-800A; Hawker 800, 800XP (STC to replace lead-acid or nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# ST00415LA	RG-390E	FAA-PMA Supplement No. 39, dd 04/23/99
Raytheon	DH.125 Series, HS.125 Series, BH.125 Series (Covers models from Series 1A – 600 B/3) (STC to replace nickel-cadmium battery) (STC to replace emergency battery only)	Concorde Battery (800) 757-0303	STC# ST01223WI	RG-125	FAA-PMA Supplement No. 65, dd 01/30/04
Raytheon	400A Series (S/N's RK-98 and after) (DA to replace 38Ah lead-acid battery)	Raytheon A/C Svc (800) 256-6012 (404) 699-9228	STC# ST02506AT	RG-380E/44* RG-380E/44L RG-380E/60L	FAA-PMA Supplement No. 44, dd 06/13/02
Raytheon	35, A35, B35, C35, 35R, D35, E35, F35, G35, H35, J35, K35, M35, 35-33, N35, 35-A33, 35-B33, P35, S35, 35-C33, E-33, F-33, G-33, V35, V35A, V35B, 35-C33A, E33A, E33C, 36, A36, F33A, F33C, A36TC, B36TC, 23, A23, A23A, A23-19, A23-24, A24, 19A, M19A, B19, B23, C23, A24R, B24R, C24R	Wilco (800) 767-7593 (316) 943-9379	STC# SA00638WI	RG35A RG-35AXC RG24-15	FAA-PMA Supplement No. 37, dd 06/22/98 Amended: dd 06/29/98

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Battery Part No.	Supplement No.
Robinson Helicopter	R-22	Robinson Helicopter (310) 539-0508	TC# H10WE	CB-25	FAA-PMA Supplement No. 11, dd 07/16/87 Amended: dd 08/10/88
Robinson Helicopter	R-22	Robinson Helicopter (310) 539-0508	TC# H10WE	RG-25	FAA-PMA Supplement No. 33, dd 09/17/97
Robinson Helicopter	R-22	Concorde Battery (800) 727-0303	STC# SR01624AT	RG-25XC	FAA-PMA Supplement No. 68, dd 02/06/04
Robinson Helicopter	R-44 (12-Volt Model)	Robinson Helicopter (310) 539-0508	TC# H11MN	RG-25XC	FAA-PMA Supplement No. 33, dd 09/17/97
Robinson Helicopter	R-22	Robinson Helicopter (310) 539-0508	TC# H10WE	RG-25	FAA-PMA Supplement No. 75, dd 02/18/05
Robinson Helicopter	R-44	Robinson Helicopter (310) 539-0508	TC# H11MN	RG-25 (12V) or RG-25XC (12V), RG24-15 (24V)	FAA-PMA Supplement No. 75, dd 02/18/05
Sabreliner	NA 265, NA 265-20, -30, -40, -70, -80 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Sabreliner	NA 265, NA 265-20, -30, -40, -70, -80 (To replace lead-acid battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44* or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92
Sabreliner	265-40, -60, -65, -70, -80 (DA to replace nickel-cadmium battery)	Jet Harbor Inc. (954) 772-2863	STC# ST01294AT	RG-380E/44*	FAA-PMA Supplement No. 36, dd 04/20/98
Sabreliner	265-65 (DA to replace nickel-cadmium battery)	Jet Harbor Inc. (954) 772-2863	STC# ST01294AT	RG-206	FAA-PMA Supplement No. 36, dd 04/20/98
Short Brothers & Harland Ltd.	SD 3-30 (To replace nickel-cadmium battery Main battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44*	FAA-PMA Supplement No. 29, dd 01/17/97
Short Brothers & Harland Ltd.	SD 3-30 (To replace nickel-cadmium Emergency Light battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-126	FAA-PMA Supplement No. 29, dd 01/17/97
Short Brothers & Harland Ltd.	SD 3-60 (To replace nickel-cadmium battery Main battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44*	FAA-PMA Supplement No. 28, dd 01/17/97 Amended: dd 02/21/97
Short Brothers & Harland Ltd.	SD 3-60 (To replace nickel-cadmium Emergency Light battery)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-126	FAA-PMA Supplement No. 28, dd 01/17/97 Amended: dd 02/21/97
Sikorsky	CH-54B	Helicopter Transport (541) 754-2400	STC# SR01241SE	RG-390E	FAA-PMA Supplement No. 78, dd 3/2/05
Sikorsky	S-76 (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# SR00091LA	RG-380E/40B	FAA-PMA Supplement No. 19, dd 08/24/95
Sikorsky	S-76A, B, C, C+ (To replace nickel-cadmium battery)	Falcon Crest Av. (800) 833-5422 (713) 644-2292	STC & STA# SR09050RC	RG-380E/44*	FAA-PMA Supplement No. 22, dd 01/23/96
Slingsby Aviation	Firefly Models T67M260 & T67M260-T3A	Slingsby Aviation (011) (44) (1751) 432474	TC# A73EU Rev. 2 BA 17, Issue 6	RG24-11M	FAA-PMA Supplement No. 27, dd 07/03/96
Socata	TBM 700 (To replace nickel-cadmium battery)	Concorde Battery (800) 757-0303	STC# SA00775LA	RG-380E/44*	FAA-PMA Supplement No. 39, dd 04/23/99
Stinson	(See Univair)				
Tamarack Helicopters	Bell UH-1F, TH-1F (To replace nickel-cadmium)	Tamarack Helicopters (406) 777-1044	STC# SR01349LA	RG-390E	FAA-PMA Supplement No. 53, dd 03/26/03
Tiger Aircraft	AA-1, AA-1A, AA-1B, AA-1C, AA-5, AA-5A, AA-5B, AG-5B	Concorde Battery (800) 757-0303	STC# SA01250WI	CB-25 CB-25XC RG-25 RG-25XC CB24-11MXC RG24-11M RG24-15M	FAA-PMA Supplement No. 71, dd 06/04/04
Twin Commander	680T, 680V, 680W, 690, 690A, 690B, 690C, 695, 695A, 690D & 695B	Concorde Battery (800) 757-0303	FAA Design Approval	CB24-380E	FAA-PMA Supplement No. 9, dd 10/12/88
Twin Commander	680T, 680V, 680W, 690, 690A, 690B, 690C, 695, 695A, 690D & 695B	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44*	FAA-PMA Supplement No. 15, dd 01/06/91
Univair (Erco)	415-C, 415-D, 415-CD (S/N 113 and up)	Univair (303) 375-8882	TC# A-718 Rev. 29, dd 07/14/05	CB-25 or RG-25	FAA-PMA Supplement No. 79, dd 11/23/05
Univair (Erco)	Ercoupe: 415-E, 415-G, 415F-1 (All S/N's) Forney: F-1A (S/N 5715 – 5729)	Univair (303) 375-8882	TC# A-787 Rev. 33, dd 07/14/05	CB-25 or RG-25	FAA-PMA Supplement No. 79, dd 11/23/05
Univair (Erco)	Forney: F-1A (S/N 5730 and up) Alon: A-2, A-2A (All S/N) Mooney M-10 (All S/N)	Univair (303) 375-8882	TC# A-787 Rev. 33, dd 07/14/05	RG-25	FAA-PMA Supplement No. 79, dd 11/23/05

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Battery Part No.	Supplement No.
Univair (Stinson)	Stinson: 108, 108-1, 108-2, 108-3, 108-5	Univair (303) 375-8882	TC# A-767 Rev. 27, dd 07/14/05	CB-35A or RG-35A	FAA-PMA Supplement No. 79, dd 11/23/05
<p>Notes:</p> <p>* - Part no. RG-380E/44 was previously part no. RG-380E/40</p> <p>Installations listed may require the purchase of an STC and/or STC Kit, aircraft modifications, etc. Batteries listed as replacements may only be eligible to replace specific models by other manufacturers. Contact the Concorde factory or the Certificate Holder for installation details</p>					