

## Connecting LYNX Series Controls to the GSMX4G, GSMV4G, IGSMV4G, or CDMA-X Communications Device

For Online Support visit: <https://mywebtech.honeywell.com>



Refer to the GSMX4G, GSMV4G, IGSMV4G or CDMA-X and LYNX PLUS, LYNXR-2 or LYNXR-I Installation Instructions for additional information and procedures. If you are installing the Communications Device with a LYNX PLUS control, ensure that the LYNXGSMEXTCB Cable Assembly is properly routed. If used, interconnecting wiring between the cable and the communications device must not exceed 20ft in length.

### Connecting the GSMX4G or CDMA-X

1. Splice the stripped end of two LYNXGSMEXTCB Cable Assemblies (P/N 600-00151) to each other as shown in Figure 1 and Table 1.




It is essential that the wires are spliced exactly as shown on Figure 1. If used, interconnecting wiring between the two LYNXGSMEXTCB Cable Assemblies must not exceed 20ft in length.

2. Connect one end of the spliced LYNXGSMEXTCB Cable Assembly (P/N 600-00151) to the receptacle on GSMX4G or CDMA-X as shown in Figure 1.
3. Connect the other end of the spliced LYNXGSMEXTCB Cable Assembly (P/N 600-00151) to the communications port on the LYNX PLUS, LYNXR-I or LYNXR-2 as shown in Figure 1. For the LYNX PLUS, ensure that the cable is properly routed as shown on Figure 2.

Table 1. Cable Assembly LYNXGSMEXTCB Splice Configuration

LYNX Series	GSMX4G or CDMA-X
Yellow	Green
Red	Black
Black	Red
Green	Yellow



LYNXGSMEXTCB-001-V1

Figure 1. GSMX4G or CDMA-X Connections




Figure 2. LYNX PLUS Cable Routing

## Connecting the GSMV4G



Power for the GSMX4G, GSMV4G, iGSMV4G or CDMA-X is provided by the LYNX Series Control. Do not install the battery in the control. Connecting the battery will significantly decrease the backup battery life of the LYNX Series controls.

1. Connect the connector of the LYNXGSMEXTCB Cable Assembly (P/N 600-00151) to the communications port on the LYNX PLUS, LYNXR-I or LYNXR-2 as in Figure 3. For the LYNX PLUS ensure that the cable is properly routed as shown on Figure 2.
2. Connect the four stripped wires from the LYNXGSMEXTCB Cable Assembly (P/N 600-00151) to the GSMV4G or iGSMV4G as shown in Figure 3.
3. Connect a jumper wire between Terminal 2 and 3 on the GSMX4G, GSMV4G, iGSMV4G or CDMA-X as shown in Figure 3.




Figure 3. GSMV4G or iGSMV4G Connections

